ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
6

Ward Name
Thanisandra

Street ID
W0999, W1011, W0842, W1311, W1307, W0846, W0882, W

Street Name
NA, 3rd Crs Thippasandra Rd Varthur, Mariyappa Lyt

Significant Landmark
Government School (Chowdappa Layout)

Segment No.
6/C-W0999/S015205

Total Length (m)
861.52

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	139.98	77.609108	13.058988	77.610390	13.058837	M0013	W0545
2	149.32	77.609076	13.058739	77.610432	13.058505	M0013	W0545
3	154.35	77.609037	13.058518	77.610425	13.058211	M0013	W0545
4	88.13	77.610287	13.050765	77.610491	13.051536	W0884	DEAD END
5	32.28	77.610000	13.050787	77.610283	13.050746	W1307	W1309
6	168.73	77.610315	13.052072	77.609904	13.050601	W0846	W1065
7	80.31	77.610029	13.052170	77.610749	13.052001	W1011	W1311
8	48.42	77.609525	13.052291	77.609966	13.052225	W0999	W1011

Work Details

History of Road / Lane / Circles

Name of the Work
Improvement to Roads and Drains at Left hand Side of Government School (Chowdappa Layout) Dasarahalli in ward no 06 Byatarayanapura Sub-Division Yel

Sanctioned Estimated Amount (Rs.)
4900000

Sanctioned Year
2016

Year
2016 - 2017

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvement to Roads and Drains at Left hand Side of Government School (Chowdappa Layout) Dasarahalli in ward no 06 Byatarayanapura Sub-Division Yelahanka zone

Job No. / Work Code
006-15-000029

Work Order No.
BBMP/EE/BTP/WO/23/2016-17

Work Order Date
30/04/2016

Period of Extention
90 DAYS

Defect Liability Period From

	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
30/04/2016	29/04/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
V. CHANDRAPPA		0.00

Phone No.	E-Mail ID
9448447181	

Field Inspection Details

Number of Trees	Any Other Information	Name
8		KRISHNAPPA

Date of Inspection	Remarks
26/11/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0999, W1011, W0842, W1311,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	26/11/2016	26/12/2016	COMPLETED
SE	VASU K M	26/11/2016	26/12/2016	COMPLETED
EE	YARAPPA REDDY	26/11/2016	26/12/2016	COMPLETED
AEE	J N LOKESH	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0999, W1011, W0842, W1311,